SUPPLEMENTAL REMARKS UNDER 37 C.F.R. § 1.111 Attorney Docket No.: Q79233

Application No.: 10/771,444

REMARKS

The undersigned would like to point out a typographical error contained in the Remarks

portion (page 8, Paragraph 1 which begins on line 1) of the Response submitted on April 22,

2008. The correction to this paragraph is provided below:

Further, none of the references cited by the Examiner disclose or even

suggest an air/liquid jet-guiding portion having a flow-out portion composed of at

least one of: notches provided in the front end portion of the air/liquid jet guiding

portion and ports formed at the front part side of the air/liquid jet guiding portion-.

Thus, reconsideration and allowance of this application are now believed to be in order,

and such actions are hereby solicited. If any points remain in issue which the Examiner feels

may be best resolved through a personal or telephone interview, the Examiner is kindly

requested to contact the undersigned at the telephone number listed below.

The USPTO is directed and authorized to charge all required fees, except for the Issue

Fee and the Publication Fee, to Deposit Account No. 19-4880. Please also credit any

overpayments to said Deposit Account.

Respectfully submitted,

/SMG/

Steven M. Gruskin Registration No. 36,818

SUGHRUE MION, PLLC

Telephone: (202) 293-7060

Facsimile: (202) 293-7860

WASHINGTON OFFICE

23373

CUSTOMER NUMBER

Date: April 30, 2008

2